




**9199 GEPE LIGHT W/ 6089 AC ADAPTER & 9280 MODIFIED SPEEDSTIR W/ 6525 AC ADAPTER
ARE PACKED IN A 8103 CARTON WITH K-0205-HP COUNTERTOP Rx 2 LAB**

NOTE: ADD 8034 (LIMITED QUANTITY ) LABEL TO SHIPPING CARTON →



PACKING LAYOUT FOR L-0205


PACKING INSTRUCTIONS FOR L-0205

STEP 1: PACK FOLLOWING PARTS IN A PLASTIC BAG

- 9199A GEPE LIGHT W/ 6089 AC ADAPTER
- 9280 MODIFIED SPEEDSTIR W/ 6525 AC ADAPTER

PLACE PLASTIC BAG IN CENTER OF 8130 CARTON


PLACE (4) 8220 IN EACH CORNER OF THE CARTON



**8103 CARTON
(see photo
on reverse)**

**STEP 2: WRAP R-0013-F AND R-0333-F IN BUBBLE WRAP
AND PLACE INSIDE THE LAB**

**STEP 3: PLACE L-0205-HP COUNTERLAB (Rx2)
IN 8103 CARTON OVER TOP OF PARTS BAG
PLACE (2) 8220 ON TOP BACK CORNERS OF THE LAB**



**8103 CARTON
(see photo
on reverse)**

STEP 4: PLACE REAGENT PACK 9277 ON TOP OF LAB IN FRONT

STEP 5: 9505 Rx2 ACCESSORY PACK IS PLACED IN CARTON W/ LAB

**STEP 6: STUFF BROWN PAPER IN CARTON AND SEAL CARTON
PLACE 7264 LABEL ON CARTON**

STEP 7: PLACE 8034 LABEL UNDER 7264 LABEL