

WHAT TYPE OF BATTERY DO YOU HAVE?

LINAK 24V BATTERY
ACP Part # F-004AB
Mfr Part # BAJ1-U026-00



The Linak battery has two (2) metal prongs on the bottom of it that connects to two (2) metal prongs on the top of the control box.

VITO 24V BATTERY
ACP Part # F-004ABV
Mfr Part # VCP100-29800



The Vito battery has a water resistant cord that comes out of the top back portion of the battery.



If your battery/control boxes do not look like these, you most likely have an integrated control box/battery. See the next page for more information.

RANGER REBEL LIFT WITH INTEGRATED BATTERY/CONTROL BOX:

INTEGRATED CONTROL BOX/BATTERY:
 OBSOLETE



Identified by the 1" diameter red button on the side

CONVERSION KIT: F-409CBK

KIT INCLUDES:

2 BUTTON LINAK HANDSET
 ACP Part # HB00-U017
Replaces Vito Handsets



LINAK 24V BATTERY
 ACP Part # F-004AB
 Mfr Part # BAJ1-U026-00



LINAK BATTERY CHARGER
 ACP Part # F-044CH
 Mfr Part # CHJ20000020F051



1 PORT LINAK CONTROL BOX
 ACP Part # F-40CBJ
 Mfr Part # CBJ2-U023-00



SCOUT LIFT WITH INTEGRATED BATTERY/CONTROL BOX:

INTEGRATED CONTROL BOX/BATTERY:
 OBSOLETE



Identified by the 1" diameter red button on the side

CONVERSION KIT: F-830

KIT INCLUDES:

4 BUTTON LINAK HANDSET
 ACP Part # HB00-U010

LINAK 24V BATTERY
 ACP Part # F-004AB
 Mfr Part # BAJ1-U026-00

LINAK BATTERY CHARGER
 ACP Part # F-044CH
 Mfr Part # CHJ20000020F051

2 PORT LINAK CONTROL BOX
 ACP Part # F-41CBJ
 Mfr Part # CBJ2-U023-00

VITO PARTS

VITO 24V BATTERY

ACP Part # F-004ABV

Mfr Part # VCP100-29800

This battery has a cable coming out of the back of it.



VITO BATTERY CHARGER

ACP Part # F-044CHV

Mfr Part # VCP100-29800

Bracket Part # INV00611



1-PORT VITO CONTROL BOX

ACP Part # F-40CBJV

Mfr Part # VCB10

Bracket Part # INV00612

Has two open holes on bottom



2 PORT VITO CONTROL BOX

ACP Part # F-41CBJV

Mfr Part # VCB10

Bracket Part # INV00612

Has 3 open holes on bottom



LINAK PARTS

LINAK 24V BATTERY

ACP Part # F-004AB
Mfr Part # BAJ1-U026-00



LINAK BATTERY CHARGER

ACP Part # F-044CH
Mfr Part # CHJ20000020F051
Bracket (1) Part # INV00716
Washers (2) Part # INV01172



1 PORT LINAK CONTROL BOX

ACP Part # F-40CBJ
Mfr Part # CBJ2-U023-00
Bracket (1) Part # INV00715
Washers (1) Part # INV01172
Has two open holes on bottom



2 BUTTON LINAK HANDSET

ACP Part # HB00-U017
Replaces Vito Handsets



4 BUTTON LINAK HANDSET

ACP Part # HB00-U010
Replaces Vito Handsets



2 PORT LINAK CONTROL BOX

ACP Part # F-41CBJ
Mfr Part # CBJ2-U023-00
Bracket (1) Part # INV00715
Washers (1) Part # INV01172
Has 3 open holes on bottom

